



## Hella: VAUXHALL ASTRA - FUEL GAUGE FAULTY

**Manufacturer:** Opel/Vauxhall

**Vehicle model:** Astra K

**Engine:** All models

**Year of manufacture:** 2015 -

**VIN:** G8000000 - G8060668

**Symptoms:** Faulty fuel gauge

**Important safety note:** Technical information and practical tips have been compiled by HELLA in order to provide professional support to vehicle workshops in their day-to-day work. The information provided on this website is intended for use by suitably qualified personnel only.



### FUEL GAUGE DOES NOT DISPLAY THE CORRECT TANK CONTENT

On the vehicles mentioned above, the fuel level display on the instrument cluster may be displayed incorrectly, so it is possible that the tank is full but a lower fill level is displayed.

Vehicles in the range of the following chassis numbers are affected: G8000000 - G8060668

A 'software weakness' could be causing the problem.

To remedy the situation, check whether a software update is available for the vehicle. An Opel dealer should be contacted for this.